


Enversör Connector®

Enversör Fiş

Seyyar makinelerde ters dönme sorunu yaşanır, Enversör fiş ile 5 saniyede tornavida yardımı ile sorunu çözün.



3 Fazlı motorlarda faz sıralamasının değişimi Enversör fiş ile 5 saniyede yapılır. (Polyamid 6)

5/16A. BC1-1505-2050
5/32A. BC1-3505-2050



IP44

5/16A. BC1-1505-2080
5/32A. BC1-3505-2080



IP44

5/16A. BC1-1505-2070
5/32A. BC1-3505-2070



IP44

5/16A. BC1-1505-2060
5/32A. BC1-3505-2060



IP44

5/16A. BC1-1505-7050
5/32A. BC1-3505-7050



IP67

5/16A. BC1-1505-7070
5/32A. BC1-3505-7070



IP67

5/16A. BC1-1505-7060
5/32A. BC1-3505-7060



IP67

5/16A. BC1-1505-2061
5/32A. BC1-3505-2061



IP44